05/10/2015 AT 04:36 PM

HML0000000

INSURANCE COMPANY

ATLANTA-CLAIM DEPARTMENT- PI

FOR SUPPLEMENT INSPECT CALL 888-299-3456 PROMPT 2

1001 WINDWARD CONCOURSE, SUITE 10

ALPHARETTA, GA 30005-2023

(800)238-6200

ESTIMATE OF RECORD

WRITTEN BY: AUTO DAMAGE APPRAISER 05/10/2015 04:36 PM

ADJUSTER: CLAIMS ADJUSTER #1 (678)317-7400

INSURED: JOHN WILKES BOOTH CLAIM #HML0000000

OWNER: LEE HARVEY OSWALD POLICY # 012345687

ADDRESS: 1000 NEW HOPE RD DATE OF LOSS: 05/09/2015 AT 09:40 AM

ATLANTA, GA 30331 TYPE OF LOSS: LIABILITY CELLULAR: (404)770-6789 POINT OF IMPACT: 6. REAR

INSPECT STARBUCKS COFFEE SHOP DAY: (404)888-7777

LOCATION: CASCADE ROAD OTHER

ATLANTA, GA 30331-0000

REPAIR 3 DAYS TO REPAIR

FACILITY: COLLISION SHOPPE LICENSE #

2007 TOYO FJ-CRUISER 4X2 6-4.0L-FI 4D UTV SILVER INT:GREY

VIN: JTEZU11F6700122345 LIC: AVI6789 GA PROD DATE: 01/2007 ODOMETER:142492

CONDITION: GOOD

AIR CONDITIONING REAR DEFOGGER TILT WHEEL INTERMITTENT WIPERS PARKING SENSORS DUAL MIRRORS LUGGAGE/ROOF RACK CLEAR COAT PAINT CONSOLE/STORAGE METALLIC PAINT POWER STEERING POWER BRAKES AM RADIO POWER WINDOWS POWER LOCKS FM RADIO STEREO SEARCH/SEEK ANTI-LOCK BRAKES (4) CD PLAYER DRIVER AIR BAG 4 WHEEL DISC BRAKES TRACTION CONTROL PASSENGER AIR BAG STABILITY CONTROL CLOTH SEATS BUCKET SEATS

RECLINE/LOUNGE SEATS AUTOMATIC TRANSMISSION ALUMINUM/ALLOY WHEELS

NO. OP. DESCRIPTION OTY EXT. PRICE LABOR PAINT

1 REAR BUMPER

O/H REAR BUMPER 2.4

WWW.DIMINISHEDVALUEOFGEORGIA.COM

N 3	3	REPL	LOWER	R COVER	R TO	1/07			1	89.96	INCL.		0.6
4	4	REPL	PREP	UNPRIN	MED E	BUMPER	LOW	ER	1				0.2
			COVEF	2 5	5**	REP	LR	ECOND	BUMPER	COVER			
W/REV	VERSE	1	212.00) II	NCL.								
			SENSO)R									
6	5		ADD F	OR REV	/ERSE	SENS					M 0.3		
N 7	7	REPL	LT CC	RNER I	PAD I	0 1/07	'		1	138.32	INCL.		0.6
8		ADD	FOR C	CLEAR (COAT							0.1	
9		REP	L PREE	UNPR	IMED	BUMPER	R CO	RNER	1				0.2
			PAD										

05/10/2015 AT 04:36 PM HML000000

1

ESTIMATE OF RECORD 2007 TOYO FJ-CRUISER 4X2 6-4.0L-FI 4D UTV SILVER INT:GREY

			DESCRIPTION					
			REAR LAMPS 11 R					
1	28.90	INC	CL.					
12			R&I RT REFLECTOR				INC	CL.
13			FENDER					
N	14*	REPL	LT FILLER TO BUMPER SILVER	1	34	.51	0.1	0.0*
	15		ELECTRICAL					
N	16	REPL	RT REVERSE SENSOR	1	182	.02	0.1	
17			REPL LT REVERSE SENSOR		1	182.	02 (0.1
18			FRONT BUMPER					
19			O/H FRONT BUMPER				2.0	
	20**	REPL	RECOND BUMPER COVER	1	185	.00	INCL.	2.4
	21		ADD FOR CLEAR COAT					1.0
N	22*	REPL	LT CORNER PAD	1	104	.84	INCL.	0.0*
N	23*	RPR	VALANCE PANEL TO 1/07				0.5*	0.8
24		OVI	ERLAP MINOR PANEL				-(0.2
25		REI	PL UPPER RETAINER		1	55.80	0.2	
		26	REPL LOWER GRILLE			1	92.98	
		INC	CL.					
	27		OTHER CHARGES					
					3			
			SUBTOTALS ==					

LINE 3 : PARTS: COMPONENT COMES UNPRIMED FROM OEM. PREPARATION IS REQUIRED. SEE ADD IF

REQUIRED OPERATION.

LINE 7 : PART NOT RECOVERED FROM ACCIDENT SCENE.

PARTS: COMPONENT COMES UNPRIMED FROM OEM. PREPARATION IS REQUIRED.

WWW.DIMINISHEDVALUEOFGEORGIA.COM

SEE ADD IF

REQUIRED OPERATION.

LINE 14: NOT RECOVERED FROM ACCIDENT SCENE, PART SUPPLIED IN COLOR.

LINE 16: OUTER RING DAMAGED, NOT SHOWN SERVICED SEPARATELY.

LINE 22: PER DATABASE PART CAN BE ORDERED IN COLOR.

LINE 23 : SCUFFED & SCRATCHED.

ESTIMATE NOTES:

*REVIEWED DAMAGES, REPAIR PROCESS & UPD W/MR. JONES, MET BRIEFLY WITH OWNER AT COFFEE SHOP, COPY OF APPRAISAL EMAILED TO HIM TO JONESROYCE@COMCAST.NET.

*LKQ AVAILABLE: RPS, APU.

*INSP MAY BE NEEDED AFTER TEAR DOWN.

*REVIEW RENTAL POLICY WITH MR. JONES, OWNER HAS CHOSEN ACE BODY SHOP FOR THE REPAIRS.

2

05/10/2015 AT 04:36 PM

HML0000000

ESTIMATE OF RECORD

2007 TOYO FJ-CRUISER 4X2 6-4.0L-FI 4D UTV SILVER INT:GREY

PRIOR DAMAGE NOTES:

RT FRONT FLARE SCRAPED.

RT DOOR DENTED AT REAR EDGE.

DOOR DINGS ON LT DOOR.

VEHICLE DIRTY WHEN INSPECTED.

RT SIDE REAR BUMPER END SCRAPED.

PARTS					1306.35
BODY LABOR	5.7	HRS	@\$	40.00/HR	228.00
PAINT LABOR	5.7	HRS	@\$	40.00/HR	228.00
PAINT SUPPLIES	5.7	HRS	@\$	28.00/HR	159.60
OTHER CHARGES					3.00
SUBTOTAL				\$	1924.95
SALES TAX	\$	1465.	. 95	@ 7.0000%	102.62
TOTAL COST OF REPAIRS				Ş	2027.57
TOTAL ADJUSTMENTS				\$	0.00
NET COST OF REPAIRS				\$	2027.57