



COMPREHENSIVE VEHICLE COLLISION REPORT



Cosmetic
Body Score

99

Meets TrueFrame
Structural Standards



Vehicle Details

Vehicle Identification No. WDDNG7DB6CA451122

Vehicle Year 2012

Make MERCEDES-BENZ

Model S550

Mileage 19,595

Inspection Details

Inspection No. 14094

Inspection Date 02/17/2014

Technician Name Tony Rached

Technician No. 1063

Location TFR116

Internet Code DNG3532

TrueFrame Reports identify vehicles that meet TrueFrame's Structural Standards. All TrueFrame inspections involve a structural review of the vehicle by a TrueFrame-certified technician. In addition, the TrueFrame Report identifies prior repairs or existing cosmetic damage to exterior body parts, resulting in an Exterior Body Score for the vehicle. Any modifications or damage to this vehicle that occur after the inspection date will not be reflected in this report, as this is a snapshot of the vehicle's cosmetic and structural condition as of the inspection date listed on the report. This TrueFrame Report does not include an evaluation of the vehicle's mechanical or interior condition, and in no way guarantees the safety of the vehicle, or that all prior repairs or existing damage will be identified.


Go to www.TrueFrameReport.com to see the terms of the TrueFrame Guarantee.

www.TrueFrameReport.com

Cosmetic Inspection

The highlighted points on this vehicle diagram indicate the general areas on the vehicle where our inspection found either prior repairs or existing cosmetic issues. These issues are not structural in nature and are considered to be purely cosmetic.

Please be aware that this diagram may not be identical in appearance to the actual vehicle being inspected.



Exterior Body Inspection (Cosmetic)

	Condition
Front Bumper Cover	Original
Hood	Original
Left Fender	Original
Left Front Door	Original
Left Rear Door	Original
Left Cosmetic Rocker	Original
Left Cab Corner	N/A
Left Quarter Panel	Original
Left Bedside	N/A
Roof	Original
Left Roof Rail	Original
Left Roof Rail	Original
Rear Bumper Cover	Original Part Repaired
Deck/Liftgate/Tailgate	Original
Right Fender	Original
Right Front Door	Original
Right Rear Door	Original
Right Cosmetic Rocker	Original
Right Cab Corner	N/A
Right Quarter Panel	Original
Right Bedside	N/A
Cladding/Mirror Housing	N/A



Engine Bay Underhood (Structural)

	Meets TrueFrame Structural Standards
Core Support	✓
Left Strut Tower/Apron	✓
Right Strut Tower/Apron	✓
Cowl Panel/Firewall	✓



Inner Body Inspection (Structural)

	Meets TrueFrame Structural Standards
A. Pillar Left	✓
B. Pillar Left	✓
C. Pillar Left	✓
D. Pillar Left	N/A
A. Pillar Right	✓
B. Pillar Right	✓
C. Pillar Right	✓
D. Pillar Right	N/A
Left Rear Strut Tower/Wheel Housing	✓
Right Rear Strut Tower/Wheel Housing	✓
Rear Body Panel	✓
Left Quarter Panel	✓
Right Quarter Panel	✓
Roof	✓

Under Body Inspection (Structural)

Meets TrueFrame
Structural Standards

A. Front Section

Front Extensions	✓
Front Reinforcement	✓
Front Left Frame Rail	✓
Front Right Frame Rail	✓
Front Cross Member	✓

B. Center Section


Center Left Rail	✓
Center Right Rail	✓
Center Left Side Floor Pan	✓
Center Right Side Floor Pan	✓
Center Left Outer Rocker Panel	✓
Center Right Outer Rocker Panel	✓
Center Left Inner Rocker Panel	✓
Center Right Inner Rocker Panel	✓
Center Cross Member	✓

C. Rear Section

Rear Left Frame Rail	✓
Rear Right Frame Rail	✓
Rear Trunk Floor Pan	✓
Rear Extensions	✓
Rear Reinforcement	✓
Rear Cross Member	✓

Measurements

Vehicle Measures Within Standards



General Report Notes



COMPREHENSIVE VEHICLE COLLISION REPORT

TrueFrame Guarantee

TrueFrame Inspections and Reports

TrueFrame inspections are designed to identify vehicles that meet our Structural Standards. Motor vehicles that meet our standards qualify to receive a TrueFrame Report. In addition, TrueFrame technicians will attempt to identify prior repairs or existing damage to structural and/or cosmetic exterior body parts. TrueFrame reports reflect the results of an in-person vehicle inspection by a TrueFrame certified technician on the inspection date listed on the report. Please be aware that any modification made to the vehicle after the inspection date (including subsequent damage, repairs, or other modifications) will not be reflected on this report, as the report is a snapshot of the vehicle's cosmetic and structural condition as of the inspection date listed on the report. A TrueFrame inspection and report does not include an evaluation of a vehicle's mechanical or interior condition, and in no way guarantees the safety of a vehicle or that any and all prior repairs or existing damage will be identified.

TrueFrame Guarantee

If a vehicle meets TrueFrame's Structural Standards and qualifies to receive a TrueFrame Report, and the frame/unibody measurements included in the TrueFrame report are incorrect by more than 5 millimeters on any one measurement, TrueFrame will provide a refund of your purchase price of the vehicle (not to exceed 100% of the current NADA clean retail value). In the event of such a refund, you will be required to transfer ownership of the vehicle and the vehicle itself to TrueFrame or its designated agent. This TrueFrame Guarantee is valid for 60 days from the date of the TrueFrame inspection. If you do not notify TrueFrame of your claim within 60 days following the inspection date listed on the TrueFrame report, TrueFrame will have no obligations under this Guarantee to you. If a vehicle is damaged or modified after the date of the TrueFrame inspection, the TrueFrame Guarantee is completely null and void.

The TrueFrame Guarantee applies only to the frame or unibody measurements in the TrueFrame report. The Guarantee does not apply to any other information provided in the TrueFrame report, including identification of paint work, replaced body parts, whether a body part was replaced with an OEM or aftermarket part, or any other aspect of the vehicle besides the frame or unibody measurements provided on the TrueFrame report. A TrueFrame inspection and report does not include an evaluation of a vehicle's mechanical or interior condition, and in no way guarantees the safety of a vehicle or that any and all prior repairs or existing damage will be identified in the report.

Disclaimer of Warranties

EXCEPT FOR THE TRUEFRAME GUARANTEE STATED ABOVE, TRUEFRAME MAKES NO WARRANTY AS TO THE INFORMATION INCLUDED IN OR THE RESULTS THAT MAY BE OBTAINED FROM USE OF THE TRUEFRAME REPORT. NO OTHER WARRANTY IS EXPRESSED AND NONE SHALL BE IMPLIED, INCLUDING WARRANTY OF MERCHANTABILITY OR WARRANTY OF FITNESS FOR A PARTICULAR PURPOSE.

TrueFrame reserves the right to share every TrueFrame Report or the information contained therein with services and/or businesses that advertise vehicles for sale or otherwise provide information on vehicles. Purchase of a TrueFrame Report by a customer shall constitute the customer's consent to such use of the TrueFrame Report. TrueFrame also reserves the right to remove any TrueFrame Report from any such service at any time.